# FIFC report

Junji Haba IPNS, KEK

# KL and K1.1 beam line


- Reminder: What was the issue?
- Possible degradation of KL beam performance by K1.1 materials in

- Reduction of KL yield


Increase of hallo neutron


• K1.1 should not endanger the ultimate sensitivity of E14.


## KL beam line at the hadron hall




## **Upstream materials**








#### Target M.C.







5456789

Neutron profile behind Cu collimator (KL coordinate)

Beam line M.C.

- · Target image is quite different in x- and y-directions
- · Different collimation and trimming lines
- · To make square beam at the front of calorimeter surface





15

29

19

5

10

-15 -10

-5

0


5


10 15

X (cm)

y-direction

leutron profile at the CsI calorimeter (z=27m)





	Core neutron	halo neutron	$K_L$
	$(E_n > 100 MeV)$	(R > 8cm  at CsI Surface,	(At the exit of
		$P_n > 2GeV/c)$	beam line)
KL line alone	$3.21 \times 10^8$	$(0.72 \pm 0.15) \times 10^4$	$(7.79 \pm 0.11) \times 10^{6}$
modified K1.1	$3.15 \times 10^8$	$(1.17 \pm 0.19) \times 10^4$	$(7.77 \pm 0.11) \times 10^{6}$
original K1.1	$1.53 \times 10^{\circ}$	$(1.28 \pm 0.20) \times 10^{4}$	$(4.55 \pm 0.05) \times 10^{9}$

Table 3: Number of the core neutrons, halo neutorns and  $K_L$ 's per spill  $(2 \times 10^{14} \text{ protons})$  at the three different configurations.


	Default	Without K1.1 materials	With K1.1-D1 only
Core n	4.7X10 <sup>8</sup>	5.0X10 <sup>8</sup>	4.8X10 <sup>8</sup>
Halo n	(4.0±0.4)X10 <sup>4</sup>	(6.3±0.5)X10 <sup>4</sup>	(3.8±0.4)X10 <sup>4</sup>


N\_halo N\_core = 8.5X10<sup>-5</sup> Neutron related background is suppressed less than that from KL decay.

# Coexistence of KL and K1.1

- Loss of KL by K1.1 beam line material is now acceptable level.
- Thanks to the hole on K1.1 D1 which is smaller than the copper collimator, the yield of hallo neutron is reduced by 60%.
- Are there any room to optimize more?

## Schedule in FY2008





- Fabrication of main beam-line collimators is delayed.
  - Final decision about the shape of the collimator hole (circular or rectangular) yet to be made.
  - Discussion on fabrication detail has not yet started. No engineering drawings!
- →FIFC recommend strongly that the group should fix the final design of the collimators, contact a manufacture and start the fabrication as soon as possible.
- In order to complete the construction of KL beam line in the first half of JFY 2009 on time, the experimental group and facility construction team should have close contact and start preparation of beam line elements needed in the early days of the construction.
- →FIFC recommends the experimental team to ask for some support by the mechanical engineering group to IPNS.

## KL beam survey

• Scheduled in Oct-Dec 2009.

#### **Charge to Beam Survey 2009**

- Measure KL yield and energy spectrum
  - Eliminate ambiguity of our expected KL number

THURSDAY STATISTICS STATISTICS

Priority 1

- A factor of ~3 difference between hadron simulation packages (FLUKA / GEANT3 / GEANT4)
- Measure core neutron

**Basic** info

Optional

- Confirm n/K ratio
  - Neutron flux estimation also depends on simulation packages (a factor of ~2 difference)

Measure halo neutron

Progresses seem also in this order.

## **Beam Survey Procedure**

- 1. Collimator alignment / adjustment
  - preparation
- 2. K<sub>L</sub> measurement
  - Main issue
- 3. Core neutron measurement
- 4. Trial of halo neutron measurement
  - Depend on beam quality, available beam time

3 Oct 2008

FIFC, T. Nomura (KEK)

8

## 2. K<sub>L</sub> Measurement

" The Welder" The second states a special state as a second second

Hodo scope

- $K_L \rightarrow \pi^+ \pi^- \pi^0$  measurement
- Simple (no magnet, no chamber)
  - Tracker

3 Oct 2008

- Scinti+WLSF
- 1cm pitch
- · 400ch in total
- Calorimeter
  - · E391a-Csl
  - 25x2 blocks

V V V V V Side View π FIFC, T. Nomura (KEK)

TT


Hodo scope

36cm.

12


40cm

Csl




### **Expected Performance**

#### Reconstructed K<sub>L</sub> mass



3 Oct 2008

#### K<sub>L</sub> Momentum resolution: {P(Recons)-P(True)}/P(True)





#### **Expected Performance**

A THE MERICANSER SHOW STATES & MARRIER AND A MARRIER STATES AND A MARRIER AND A MARRIER AND A MARRIER AND A MAR

#### Acceptance vs K<sub>L</sub> momentum

#### (cf.) expected K<sub>L</sub> spectrum





Rate capability is an issue

With/Without  $\gamma$  absober

0.3


0.4

Had4

0.6

# FIFC's view


- "No redundancy measurement"
  - Kinematics just determined by all the measurements other than KL mass constraint
  - Very little tolerance for background hit. Stability against background is not clear.
- Independent check/ measurement of acceptance/ efficiency seems important.
- Stability /monitor of primary beam condition (intensity, position, time structure ...) is essential. Not yet been investigated fully.



All the necessary arrangements for a formal application of radiation safety (April09) should be started immediately.

# Trouble in the SKS renovation

## **Modification of Cooling System**



- 300W He refregirator
  - Cold Box
  - (Medium) Compressor
  - He Transfer line
  - LN<sub>2</sub> storages
  - etc...
- Cu current leads


Head load (operation) ~ 5W

- 3.5W GM-JT cryo-cooler x 3
  - shield cooler
- HTC current leads with GM cryo-cooler

#### can maintain liquid state of He

FIFC2008-10-3


# Shape of Yoke & Coil using in the Calculation



# Something happened during disassemble, transport .....




### Earth fault found in the TOSHIBA factory (July)



ターン数: 330,330,330 (HFCoil), 350,350,420 (LFCoil) ただし、総ターン数は、2108ターン

地絡場所: 1S端子から3.4m(コイル半周)のところ

9



コイルロ出し線 冷凍機ポートへ




- 修理はほぼ不可能
  ヘリウム容器の最内部
  非破壊検査(X線)も望み薄い
  - ▶ 容器壁 厚さ30mm, ステンレス

	SKS完成時(1991)	対策前	対策後
コイルターン数 [/Coil]	2108		1778
インダクタンス [H]	90		78.4
定格(最高)電流 [A]	500	400*	400
中心磁場 [T]	3.0	2.7	2.48
蓄積エネルギー [MJ]	11.3	???	6.3

\*1993年 大クエンチ・コイルサポート修理後、400A以上の使用を禁止

電流と中心磁場



# SKS移設・コイル改造作業

- 2008.1 Disassemble the yoke
- 2008.7 Coil insulation test @ TOSHIBA Earth fault found
   2008.8 Coil renovation & Insulation @1kV
- 2008.9 Yoke transport to Tokai
- (2008.10.E Coil renovation finished @TOSHIBA
- (2008.11 Cooling test
- (2009.1-2? Assemble the yoke

- No time to map the modified field.
- Calculated filed map will be used in future experiment in J-Parc.
- Detailed study with the calculated map has been made.
  - Sks0-high resolution
    - No serious effect once enough calibration data collected.
  - SksPlus
    - No prolem in acceptance, slight worse resolution
  - SksMinus
    - Slight change in acceptance (need setup modification), resolution dominated by target material

# SKS trouble summary

- Cause of the trouble not identified.
- Renovation and test are reasonable.
- Preparation is necessary for future happening of another earth fault.
- Thanks to the new refrigerator system, thermal cycling can be much less frequent. (regulation framework can be changed for simpler operation/shift)